5/05

SPLIT

DART AEROSPACE LTD	Work Order:	221231
Description: Mounting Lug	Part Number:	D3235-1
Dwg: D3235 Rev. A	Qty:	500/08
		Page 1 of 1

Step	Location	Procedure	Ву	Date	Qty
1	DC	Issue Traveler	+	05,01.03	500
2	MV	Cut D2423 extrusion to 0.820" Batch: BZLZOZ	50	05.02.23	Sœ
3	PK	Machine as per Follo FA369 and Dwg D3235 Identify as D3235-1 (9500 PC)	u	050303	170X
4	ac2	Inspect parts as they come off the CNC machine Referred + Luspect for frans - damage	CL	05/03/17	108
5	MV	Deburrand Tumble WA			
6	QC8°	Second check- INSPACT JUNEVIOUS	P	05.13.14	108
7	FP	Acid etch and Alodine as per QSI 005 4.1	NF8	7-04-05	1
8	QC5	Inspect Acid etch	M	05 04 07	108
9	FP	Powder Coat Gloss White (Ref: 4.3.5.1) as per QSI 005 4.3	M	05 04 07	108
10	QC3	Inspect Powder Coat	CL	05/04/08	109
11-	QC5	Inspect work-to Step 10			
12	ST	Identify and Stock	CL	9564/08	103
13	AC	Cost / part 13, 88	Suc	05.04-12	
14	DC	Close W/O / 3 . 89 Inspect Level 21	H	05.04.12	108


RevDateChangeRevised ByApprovedA04.04.19New issueKJ/JLMApproved


RELEASED





DESIGN	DRAWN BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA		
CHECKED	APPROVED	DRAWING NO. D3235	REV. A SHEET 1 OF 1	
DATE	111	TITLE	SCALE	
04.03.02	2	MOUNTING LUG	1:1	
Δ	04 03 02	NEW ISSUE		





D3235-1 MOUNTING LUG

MAKE FROM EXTRUSION D2423

BREAK ALL EDGES 0.000-0.015 FINISH: ACID ETCH AND ALODINE PER DART QSI 005 4.1

POWDER COAT WHITE (4.3.5.1) PER DART QSI 005 4.3 TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED

WORK ORDER

L LOUT NOTICE

NO. 22123

Copyright @ 2004 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.